


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-030	Smoke	8/18/2008	ADS/TM	S11WW_016MH	Dry	Yes	1,443.49



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-030	Smoke	8/18/2008	ADS/TM	S11WW_016MH	Dry	Yes	1,443.49

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11WW_017G1	S11WW_017MH	S11WW_010MH	253.1889	8
S11WW_010G1	S11WW_010MH	S11WW_008MH	254.745	8
S11YY_020G1	S11YY_020MH	S11WW_017MH	84.40033	8
S11WW_008G1	S11WW_008MH	S11WW_016MH	317.7194	8
S11YY_006G1	S11YY_006MH	S11YY_009MH	79.94872	8
S11YY_009G1	S11YY_009MH	S11YY_020MH	170.2551	8
S11WW_016G1	S11WW_016MH	S11UU_013MH	283.2369	8

Observations & Photos

Obs_ID S1028-030-OB01

Address 3404 Ellamont Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_016MH

Comments Smoke from cleanout in front yard. 3404 Ellamont Rd.



Picture \S1028-030-OB01-P01.jpg

Comments Front of house, 3404 Ellamont Rd.

Obs_ID S1028-030-OB02

Address 3405 Ellamont Rd


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_016MH

Comments Smoke from cleanout in front yard. 3405 Ellamont Rd.



Picture \S1028-030-OB02-P01.jpg

Comments Front of house, 3405 Ellamont Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-030	Smoke	8/18/2008	ADS/TM	S11WW_016MH	Dry	Yes	1,443.49

Obs_ID S1028-030-OB03

Address 3406 Ellamont Rd


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_016MH

Comments Smoke from cleanout in font yard. 3406 Ellamont Rd.



Picture \S1028-030-OB03-P01.jpg

Comments Front of house, 3406 Ellamont Rd.
